

HGWSTESTER

Foot Grounder - Wrist Strap Tester

This tester allows associates to test their own wrist straps, foot grounders or shoes. The integrated test meter measures the resistance through person and the wrist strap or the foot grounder that they are wearing. Results are immediate and easy to understand. Red lights and a warning tone are issued for a resistance that is too high or too low. A green "Pass" light indicates a resistance in the acceptable range.

Standards

Useful for audit testing required by ANSI/ESD S-20.20, EIA 625, MIL-STD-1686.

Specifications

Tester:
 Power: 9 volt battery (included) or adapter
 Range: Selectable: 750 k to 10M or 900k to 35M ohms


Indicators:
 Pass: Green Light
 Fail Low: Red Light and Tone
 Fail High: Red Light and Tone
 Touch Plate: Stainless Steel.

Wall Plate:
 Yellow plastic. Includes: Instructions, mounting holes, connections for test meter and floor plate.


Floor Plate:
 Construction: Stainless Steel on insulator.
 (Includes connector lead to wall plate.)

Part Numbers

HGWSTESTER	Foot Grounder - Wrist Strap Tester: Includes Tester, Wall Plate and Floor Plate
AVAILABLE SEPARATELY	
WALLPLATE	Plastic holder and connector for Tester.
FLOORPLATE	Contact plate for foot grounders
WSCHECKER	Tester



Easy to Install



P R O D U C T D A T A S H E E T

Foot Grounder - Wrist Strap Tester

PRODUCT
 FOOT GRINDER - WRIST STRAP TESTER

ITEM NUMBER
 SEE ABOVE

DATASHEET
 1146-A



US and Canada: 866-722-3736
 Fax: 866-722-3735
 Intl: 919-774-3808
 Fax: 919-774-1287
 3010 Lee Avenue Sanford, NC 27330
 email: info@staticcontrol.com
 www.StaticControl.com ©